

M. Sathyanarayanan

From: service <service@ronganpower.com>
Sent: Tuesday, October 13, 2015 11:17 AM
To: Wei Zhang
Cc: FLEET-HK-TECH5
Subject: Re: Urgent! Main Engine is difficult to start - Shandong Hai Yao

Importance: High

Dear Mr.Zhang

Regret to hear this problem first.

ICU leakage more or less will be happened when ship use LSMGO due to very low oil viscosity, in this case there is no any other better way to solve the problem but to use HFO to run engine or supply new ICU or ICV repair kits to replace the existed ones.

Best regards!

2015-10-13

技术服务部/Technical Service Dept.

激情卓越 Passion & Excellence

=====

合肥熔安动力机械有限公司

HEFEI RONG AN POWER MACHINERY CO.,LTD

安徽省合肥市宿松路9166号(230601)

9166 Susong Road,Hefei,Anhui,China

电话/Tel: 0551-8788888-8828, 传真/Fax: 0551-8788888-6087

手机/Mb:13855128681, 电邮/Email:wang.ziwei@ronganpower.com

发件人：Wei Zhang

发送时间：2015-10-13 10:47:53

收件人：service@ronganpower.com

抄送：FLEET-HK-TECH5

主题：Urgent! Main Engine is difficult to start - Shandong Hai Yao

Dear Mr. Ji:

Pls note subject vessel main engine is difficult to start due to abnormal oil leaking from ICU when ship use LSMGO, kindly find below mentioned ICU oil leakage test result from vessel (observed during one start time) which for your kind perusal.

SNo.1 unit: about 150 mls

No.2 unit: about 180 mls

No.3 unit: about 150 mls

No.4 unit: about 150 mls

No.5 unit: about 150 mls

kindly note that subject vessel was unable to berth due to said main engine start problem on yesterday Oct.12.2015 a.m. (lt) and ship has to wait at present anchorage till the main engine start problem is rectified, we have ordered required ICV repair kits and which is expected to reach Point Comfort around Oct.16.2015, in order to minimize ship waiting time at present anchorage thus to avoid further losses to the ship owners, we would

appreciate if your good maker could provide us valuable guidance and comment in order to improve and rectify the main engine start problem when use LSMGO.

Details of vessel and engine mentioned on below FYI:

Vessel name: Shandong Hai Yao

IMO no.: 9591533

Shipyard/Hull nom: Rong Sheng/Hull 1146

Engine Type: RONGAN 5RT-flex58T-D (Tier II) Engine no.: RE-0041A

Your prompt revert and assistance would be highly appreciated.

Best Regards/Zhang Wei

FML-HK-TECH5/Superintendent

As agents only

Tel: +852 2298 8356

Fax: +852 2528 1550

Mob: +852 9016 9681

E-mail: zhangwei@fleetship.com

www.fleetship.com

SAFE CREW, SAFE SHIPS AND CLEAN SEA